

Summary of Facility Information in the County of Rosebud

Owner Name and Address: St Labre Indian School Education Association 1000 Tongue River Road Ashland MT 59003 Phone: (406) 666-2215

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4400701	St Labre Indian School UST		Ashland	59003	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
7 / 10 Currently in Use	1957	12/1/1993 12 / No	Gasoline 15,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div> A B C D E F G H I J K L </div> <div> B D E F G H I K L </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Cleatus Stevenson PO Box 436 Ashland MT 59003 Phone: (406) 784-2400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4401892	Western Pump	US Highway 212	Ashland	59003	(406) 784-2400

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	3098	2/1/1993 13 / No	Gasoline 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	3099	2/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	3100	10/29/1997 08 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Northern Cheyenne Tribe PO Box 10 Lame Deer MT 59043 Phone: (406) 477-6794

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4413200	Cheyenne Depot 2	US Highway 212 & Mission Road	Ashland	59003	(406) 784-2522

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4420	7/30/1993 12 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	4421	7/30/1993 12 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	4422	7/30/1993 12 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Temporarily Out of Use	4423	7/30/1993 12 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	4424	7/30/1993 12 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Northwestern Corp 40 E Broadway St Butte MT 59701 Phone: (406) 497-3000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4401432	Colstrip 500 KV Substation		Colstrip	59323	(406) 497-3000

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
1 / 01 Currently in Use	3998	4/30/1982 24 / No	Diesel 2,500	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: PP & L Montana LLC 303 N 28th St Ste 400 Billings MT 59101 Phone: (406) 268-2326

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4406584	Colstrip Steam Electric Station Units 3 &	601 Willow Ave Units 3 & 4	Colstrip	59323	(406) 748-5026

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / S10-23 Temporarily Out of Use	3703	5/1/1979 27 / Ye	Diesel 500,000	Unknown None	Bare Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> D E F G H I J K L </div> </div>	Yes Yes Yes Yes
5 / S10-24 Temporarily Out of Use	2863	5/1/1979 27 / Ye	Diesel 40,000	Unknown None	Bare Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> D E F G H I J K L </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4408689	Town Pump Inc Colstrip	112 Willow Ave	Colstrip	59323	(406) 748-3533

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	4787	4/12/1975 31 / No	Diesel 15,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently in Use	4788	4/12/1975 31 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
3 / 03 Currently in Use	4789	4/12/1975 31 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
4 / 04 Currently in Use	4790	4/12/1975 31 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
5 / 05 Currently in Use	4791	4/12/1975 31 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
6 / 06 Currently In Use	4792	1/1/2000 06 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
7 / 07 Currently In Use	4793	1/1/2000 06 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: PP & L Montana LLC 303 N 28th St Ste 400 Billings MT 59101 Phone: (406) 268-2326

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4408921	Colstrip Steam Electric Station Willow Av	601 Willow Ave	Colstrip	59323	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2864	8/1/1991 14 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2865	8/1/1991 14 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: TLC Enterprises Inc PO Box 549 Billings MT 59103 Phone: (406) 245-4531

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4409736	Colstrip Super Stop UST	MT Highway 39 & Commerce Circle	Colstrip	59323	(406) 748-4514

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3216	2/13/1988 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	4508	2/13/1988 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3218	12/13/1988 17 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	3219	2/13/1988 18 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Otto Bendewald PO Box 86 Forsyth MT 59327 Phone: (406) 356-7644

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4401244	Kum and Go Store 819	1017 Front St	Forsyth	59327	(406) 356-2885

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	1393	2/24/1992 14 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1394	2/24/1992 14 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1395	2/24/1992 14 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Rosebud County Road Dept PO Box 1117 Forsyth MT 59327 Phone: (406) 346-2261

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4401288	Rosebud County Road Dept	US Highway 10	Forsyth	59327	(406) 356-2261

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 06 Currently in Use	1859	4/1/1991 15 / No	Diesel 4,000	STI-P3 Double-Walled	Galvanized Steel Cathodically Protected	U.S. Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 07 Currently in Use	1860	4/1/1991 15 / No	Diesel 10,000	STI-P3 Double-Walled	Galvanized Steel Cathodically Protected	U.S. Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 05 Currently in Use	1858	4/1/1991 15 / No	Gasoline 6,000	STI-P3 Double-Walled	Galvanized Steel Cathodically Protected	U.S. Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Rosebud Health Care Center 383 N 17th Ave Forsyth MT 59327 Phone: (406) 356-2161

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4405262	Rosebud Health Care Center	383 N 17th Ave	Forsyth	59327	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	4343	9/1/1991 14 / No	Diesel 500	STI-P3 Double-Walled	Bare Steel Cathodically Protected	U.S. Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (●) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Prince Inc PO Box 440 Forsyth MT 59327 Phone: (406) 356-2137

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4406209	Prince Inc Forsyth	W Frontage Road	Forsyth	59327	(406) 356-2137

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently In Use	4532	10/1/1998 07 / No	Diesel 10,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
6 / 06 Currently In Use	4533	10/1/1998 07 / No	Gasoline 5,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4409356	Town Pump Inc Forsyth	974 Front St	Forsyth	59327	(406) 356-7952

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
11 / 11 Currently In Use	4736	10/21/2002 03 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		<input checked="" type="radio"/>		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		<input checked="" type="radio"/>		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
12 / 12 Currently In Use	4737	10/21/2002 03 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		<input checked="" type="radio"/>		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		<input checked="" type="radio"/>		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
13 / 13 Currently In Use	4755	11/20/2002 03 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
14 / 14 Currently In Use	4738	10/21/2002 03 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		<input checked="" type="radio"/>		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		<input checked="" type="radio"/>		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
15 / 15 Currently In Use	4756	11/20/2002 03 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
16 / 16 Currently In Use	4757	11/20/2002 03 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					





































Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Pelican Oil Co PO Box 549 Billings MT 59103 Phone: (406) 245-4531

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4410824	Home Oil Co	200 Main St	Forsyth	59327	(406) 347-5210

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																										
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																										
1 / S1 Currently in Use	3981	4/14/1940 66 / Ye	Gasoline 10,000	Asphalt Coated or Bare Steel None	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td></td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J		L						E	F	G	H	I	J	K	L	Yes Yes Yes Yes	
A	B	C	D	E	F	G	H	I	J		L																							
					E	F	G	H	I	J	K	L																						
2 / S2 Currently in Use	3982	4/14/1940 66 / Ye	Diesel 10,793	Asphalt Coated or Bare Steel None	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td></td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J		L						E	F	G	H	I	J	K	L	Yes Yes Yes Yes	
A	B	C	D	E	F	G	H	I	J		L																							
					E	F	G	H	I	J	K	L																						
3 / S3 Currently in Use	3983	4/14/1940 66 / Ye	Gasoline 5,552	Asphalt Coated or Bare Steel None	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td></td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J		L						E	F	G	H	I	J	K	L	Yes Yes Yes Yes	
A	B	C	D	E	F	G	H	I	J		L																							
					E	F	G	H	I	J	K	L																						
4 / S4 Currently in Use	4916	5/25/2004 02 / Ye	Diesel 10,793	Concrete None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td></td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J		L		B				D	E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J		L																							
	B				D	E	F		H	I	J	K	L																					
5 / S5 Currently in Use	4917	5/25/2004 02 / Ye	Diesel 17,332	Concrete None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td></td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J		L		B				D	E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J		L																							
	B				D	E	F		H	I	J	K	L																					
6 / S6 Currently in Use	4918	5/25/2004 02 / Ye	Diesel 10,040	Concrete None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td></td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J		L		B				D	E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J		L																							
	B				D	E	F		H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: BIA Northern Cheyenne Agency PO Box 40 Lame Deer MT 59043 Phone: (406) 477-6211

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0202192	BIA Northern Cheyenne Agency Bldg 41	Highway 315 N	Lame Deer	59043	(406) 477-6212

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
22 / S22 Currently In Use	4669	5/1/2000 06 / No	Heating Oil 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>No</div> <div>Yes Yes Yes</div> </div>	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Rosebud

Owner Name and Address: Northern Cheyenne Tribe PO Box 10 Lame Deer MT 59043 Phone: (406) 477-6794

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4410431	Cheyenne Depot	Cheyenne Ave & 4th St	Lame Deer	59043	(406) 477-6794

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently in Use	4726	1/30/1987 19 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
2 / 01 Currently in Use	4724	1/30/1987 19 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
3 / 02 Currently in Use	4725	1/30/1987 19 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
4 / 04 Currently in Use	4727	1/30/1987 19 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed